

FORM NO.

Certificate of Stability for Continued Use of School

- 1. Name of the Building: Shri Swaminarayan School, Ranip
- 2. Address: F.P. 24, Nr. Kasturisharnath Mahadev Temple, G.S.T. Crossing, Ranip, A'Bad
- 3. Phone No./Email: harikrushnaseemi@yahoo.com
- 4. Name of the Occupier of the Premises: Shastri Swami Premswarupdasji
- 5. Use of Occupancy: Educational
- 6. No. of floors: Ground, First

I certify that I have inspected the premises, the plans of which have been approved by the Municipal Corporation (or other relevant authority) of _____ vide _____ dated _____ and have reviewed it internally and externally. I am of the opinion that the structure of the said premises appears in sound condition and that its /their stability will not be endangered by its continued use for which the building was intended.

Attached is my Survey Report.

Signature:

Harish A. Shah
 Harish A. Shah B. E. (Civil)
 35, Veernagar Co-op. Hou. Soc. Ltd.
 Bhimjipura, AHMEDABAD-380013.
 AMC STR Lic No. SD-0280150516R

Experience:

20 Years

Affiliations/Memberships to Professional Associations: Municipal Corp.

Licence No. of Municipal Corporation (if not applicable, membership no of IIE)
 AMC STR Lic No. SD-0280150516R

Address: 35, Veernagar Co-op. Hou. Soc. Ltd.
 Bhimjipura A'Bad

Date: 13-12-11

PRINCIPAL श्री स्वामिनारायण विश्वमंगल गुरुकुल

SHREE SWAMINARAYAN INTERNATIONAL SCHOOL
 G.S.T. RLY CROSSING, RANIP, AHMEDABAD.


Harish A. Shah
 PRINCIPAL

SHREE SWAMINARAYAN INTERNATIONAL SCHOOL
 G.S.T. RLY CROSSING, RANIP, AHMEDABAD.


13/12/11
 100002 (AMM) 11/12/11

10.0 SCHOOL SURVEY FORM

1.	School Name	Shri Swaminarayan Secondary School, Gand
2.	School ID	harsikrshnswami@yahoo.com
3.	School category (Pre-Primary - A, Primary- B, Secondary - C, Higher secondary - D)	Secondary - C
4.	Address a) Location b) Village/Town/City: c) Census Code: d) Taluka: e) District: f) Nearest Town	F.P. 24, Nr. Keshavnath Mahadev Temple, G.S.T. Crossing, Rannip Ahmedabad
5.	GPS Coordinates of School (Any center point)	----- N ----- E ----- m
6.	Communication System a) Telephone b) Fax c) Internet / Email d) Any other emergency communication facility	9825009408 9879614190 harsikrshnswami@yahoo.com 9879628282
7.	School Area (meter square) a) Plot Area: b) Footprint Area: c) built up Area	4804 1907 2111.80
8.	Number of (Indicate as per shifts if any) a) Pupils b) Teachers c) Other Staff d) Physically challenged staff	
9.	Number of Rooms a) Class Rooms b) Other Rooms	6 Room G.F. 6 Room G.F.


 PRINCIPAL
 SHREE SWAMINARAYAN INTERNATIONAL SCHOOL
 G.S.T. CROSSING, RANNIP, AHMEDABAD.

PRINCIPAL
 SHREE SWAMINARAYAN INTERNATIONAL SCHOOL
 G.S.T. CROSSING, RANNIP, AHMEDABAD.

10.	Passage and Veranda a) Width of Passages (Less than 1.5m) b) Veranda Area (In m2)	2-16 mtr.
11.	Width of Stair flight (m)	1-52 mtr.
12.	Number of Exit	one
13.	Compound Wall (Yes/No, if yes then height of wall)	Yes 1-52 mtr.
14.	Year of Construction	2012
15.	Plan shape : Draw Plan and elevation with major dimensions (See also last sheet)	
	<p>Approved Plan Attached</p> 	
16.	Plan Regular/ Irregular : If irregular. T- shape/L-shape/U-shape/Cruciform/other complex shape:	

17.	Number of storeys : a) Basement (Yes / No) b) Storeys c) Mezzanine (Yes / No)	No No
18.	Typical storey height (m)	3.05 mtr
19.	Stilt at Ground floor: (Yes/No)	-
20.	Type of load carrying system : a) Stone Masonry Bearing walls b) Brick Masonry Bearing walls c) RCC Frames d) Steel Structure e) Other (elaborate)	R.C.C. Frames
21.	Partition walls : Reinforced concrete/ Wood/ Masonry/ Mixed/ Other(Specify)	masonry
22.	Floor slabs : Reinforced concrete/Wood/Other(Specify)	Concrete
23.	Floor Finish: Wood/ Ceramic/ Mosaic /IPS/ Other(specify)	Ceramic
24.	Roof : Reinforced concrete flat roof/ Reinforced concrete sloping roof/ Wood/Asbestos/Metal sheets/ Other. (Specify)	Reinforced concrete sloping roof
25.	Seismic/other disaster safety features in the building(in case of masonry) a) Plinth Band b) Lintel Band c) Roof Band d) Other features Seismic/other disaster safety features	plinth Band Lintel Band Roof Band

	<p>In the bulding(In case of RC frame)</p> <p>a) Proper framing grid of more than 3 frames of min 3 bays each in both direction</p> <p>b) Max cantilever projection (m)</p> <p>c) Any floating columns? If yes, give details</p>	
26.	<p>Quality of Building</p> <p>a) Workmanship</p> <p>b) Maintenance</p> <p>Grade on a scale of 5) (5 for excellent and 1 for poor)</p>	5
27.	<p>Any Existing visible damages (Yes/No)</p> <p>If yes: Description</p>	No
28.	<p>Last repair & reconstruction works</p> <p>a) Repaired (Year)</p> <p>b) Strengthened (Year)</p>	New Construction
29.	<p>Fire Protection : (Yes / No)</p> <p>a) High voltage electric transformers not protected within campus or 25m periphery of school</p> <p>b) Loose electric wares within campus and not fenced</p> <p>c) Any highly flammable/ hazardous goods lying in the school or surrounding buildings</p> <p>d) Petrol Pump (25m periphery of school)</p> <p>e) Hydrants (Yes / No)</p> <p>f) Fire extinguishers (Yes / No)</p> <p>g) Fire Alarms (Yes / No)</p> <p>h) Smoke detectors(Yes/No)</p> <p>i)</p>	Yes 9. Fire extinguisher

30.	Surroundings of School a) High Rise/Low Rise Buildings b) Congested/Market Area c) High traffic/Normal traffic/ Low traffic Area	Low Rise Low traffic Areas
31.	Technical documentation available a) Architecture (Yes / No) b) Structural design (Yes / No)	Yes Yes
32.	Site - Soil conditions : Rock/Firm/Medium/Soft	Medium
33.	Slope : Flat /Slight slope/Moderate slope/Steep slope	Flat
34.	Seismic exposure : (To be filled by Reviewing Engineer) a) Seismic Zone b) Unknown	—
35.	History of Disaster (Mention month, year, frequency and damages due to the disaster) a) Earthquake b) Cyclone c) Floods d) Fire	—
36.	Awareness in School a) Among Teachers b) Among Students c) Any Formal course/training for disasters	—
37.	Preparedness for Disasters a) Contingency plan b) Escape Routes c) Safe Shelters during cyclone d) Other preparedness	—


PRINCIPAL
SHREE SWAMINARAYAN INTERNATIONAL SCHOOL
G.S.T. RLY CROSSING, RANIPAHMEDABAD.

SHREE SWAMINARAYAN INTERNATIONAL SCHOOL
G.S.T. RLY CROSSING, RANIPAHMEDABAD.

38.	Photographs	
39.	Remarks & recommendations (Yes / No)	

The above parameters are indicative and interested consultant may comment to achieve the objective of study.

Surveyor

Name:

Signature:

Date:

Building ID

(Line Plan of the School Campus and building IDs)

Principal

Name:

Signature:

શ્રી સ્વામિનારાયણ વિશ્વમંગલ ગુરુકુલ

મહાશયી રસદી

PRINCIPAL

SURE SWAMINARAYAN INTERNATIONAL SCHOOL
G.S.T. RLY CROSSING, RANIP, AHMEDABAD.